

FIG. 1A




F I G. 1B

	C1	C2	СЗ	В1	B2	В3	F1	TRANSMISSION GEAR RATIO
1st	0			(0)			0	3.478
2nd	0				0			2.000
3rd	0					0		1.320
4th	0	0						1.000
5th		0				0		0.871
6th			0			0		0.680
7th		0			0			0.597
Rev			0	0				1.478

F I G. 2





F I G. 3B

	C1	C2	СЗ	B1	B2	ВЗ	F1	TRANSMISSION GEAR RATIO
1st	0			(0)			0	3.000
2nd	0				0			1.667
3rd	0					0		1.400
4th	0	0						1.000
5th		0				0		0.800
6th		0			0			0.667
7th			0			0		0.400
Rev			0	0				2.000 ·

F I G. 4

